

1074 1962



# National Transportation Safety Board

Washington, D.C. 20594

## Safety Recommendation

Date: August 3, 1987  
In reply refer to: A-87-103

Honorable T. Allan McArtor  
Administrator  
Federal Aviation Administration  
Washington, D.C. 20591

The National Transportation Safety Board has completed the investigation of an accident that occurred in Conway, South Carolina, on November 9, 1986, involving a Cessna 152, N6537P. <sup>1/</sup> The investigation disclosed that while climbing at 2,500 feet the airplane vibrated violently and lost engine power. A forced landing was made in an open field, and during rollout the aircraft nosed over and came to rest inverted. The certificated flight instructor and student pilot on board were not injured. Examination of the wreckage revealed that one blade of the propeller, design number 1A103, serial number 773241, had separated and was missing. The propeller is a fixed pitch, solid propeller of the "gull wing" design with each blade extending somewhat forward from the hub. The propeller was manufactured by McCauley Accessories Division of Cessna Aircraft Company (McCauley) and had 3,425.1 total hours at the time of the accident.

The recovered portion of the propeller was examined at the Safety Board's Materials Laboratory. One blade of the propeller was separated about 3 inches from the centerline of the hub. An examination of the fracture surface on the blade revealed characteristics typical of fatigue cracking over more than one-half of the blade's cross section at the fracture location. The fatigue cracking initiated in the leading edge portion of the radius between the forward face of the propeller hub and the forward face of the broken blade. An examination of this area revealed that the radius was slightly undercut and contained chordwise sanding scratches. These scratches were much more readily visible after the paint was removed from the radius area. Examination of the fatigue origin area with a scanning electron microscope disclosed that fatigue initiation was from a small area along one of the sanding scratches. Similar chordwise sanding scratches were also found throughout the radius between the front face of the hub and the front face of the intact blade.

The Safety Board is aware of one additional McCauley design number 1A103 propeller that failed in a manner very similar to the propeller involved in the Conway accident. The other propeller, serial number 770439, was also installed on a Cessna 152 and had 1,930 hours of total time when it failed in 1980. The examination of this propeller was conducted by an independent laboratory and the report was reviewed by a Safety Board metallurgist. Fatigue cracking characteristics were found over much of this blade, and crack initiation was from the same radius as the propeller involved in the Conway accident. Chordwise sanding scratches were also found in this radius.

<sup>1/</sup> NTSB Field Accident Report: ATL-87-LA-019. Accident Brief: File No 2171.


The design number 1A103 propeller was first manufactured in 1977. A representative of McCauley indicated that the serial number 770439 propeller was made in 1977 and the serial number 773241 propeller was made in 1978. The representative also indicated that the radii between the front face of the hub and the front face of the blades on some of the design number 1A103 propellers produced during the early years of manufacture may have been sanded by hand after the area was machined. However, McCauley has no documentation on when the sanding may have occurred. In December 1984 the engineering drawing for the design number 1A103 propeller was revised by adding a surface finish requirement of 125 root mean square micro-inch. However, at the time that the two failed blades were manufactured, there was no surface finish requirement. The surface in the sanded areas on the propeller from the Conway accident visually appeared slightly rougher than the current requirement as a result of the presence of the sanding scratches.

The Safety Board is concerned that there may be additional McCauley design number 1A103 propellers with sanding scratches in the radii between the front face of the hub and the front face of the blades, that this condition may lead to fatigue crack initiation and to failure of the propeller, and that failure of the propeller can cause a serious accident.

Therefore, the National Transportation Safety Board recommends that the Federal Aviation Administration:

Issue an Airworthiness Directive to require that all McCauley design number 1A103 propellers with a specified minimum number of hours be inspected for evidence of sanding scratches and cracks in the radii between the front face of the hub and the front face of the blades; this inspection should be conducted with the paint removed from the radii. In the event that sanding scratches or cracks are evident in the radii between the front face of the propeller hub and the front face of the propeller blades, specify appropriate criteria and procedures for repair or removal from service. (Class II, Priority Action) (A-87-103)

BURNETT, Chairman, GOLDMAN, Vice Chairman, and LAUBER, NALL, and KOLSTAD, Members, concurred in this recommendation.

  
By: Jim Burnett  
Chairman



Brief of Accident (Continued)

File No. - 2171      11/09/86      CONWAY, SC      A/C Reg. No. N6537F      Time (Lcl) - 1640 EST

Occurrence #1      AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION  
Phase of Operation      CLIMB

Findings(s)

1. PROPELLER SYSTEM/ACCESSORIES, BLADE - FATIGUE
2. PROPELLER SYSTEM/ACCESSORIES, BLADE - FAILURE, TOTAL.

Occurrence #2      LOSS OF POWER(TOTAL) - MECH FAILURE/MALFUNCTION  
Phase of Operation      DESCENT - EMERGENCY

Findings(s)

3. MIXTURE CONTROL - LOSS, TOTAL

Occurrence #3      FORCED LANDING  
Phase of Operation      DESCENT - EMERGENCY

Occurrence #4      NOSE OVER  
Phase of Operation      LANDING - ROLL

Findings(s)

4. TERRAIN CONDITION - SOFT

----Probable Cause----

The National Transportation Safety Board determines that the Probable Cause(s) of this accident is/are finding(s) 1,2.